




1/10

FIG. 1




2/10  
FIG. 2



3/10  
FIG. 3

4/10

FIG. 4



5/10  
FIG. 5





FIG. 6



6/10  
FIG. 7






FIG. 8

WHEN AIR AMOUNT REMAINS UNCHANGED



7/10  
FIG. 9

8/10  
FIG. 10

WHEN ISC OPENING REMAINS UNCHANGED






FIG. 11

WHEN ISC CHANGE INSTRUCTION REMAINS UNCHANGED



9/10  
FIG. 12



20/541214

Rec'd PCT/PTO 30 JUN 2005

10/10  
FIG. 13

